



ThunderCore®

Rope Thread!



“PCN” Shanks and Accessories

Part #	Description
PCNSPL12	12" Spline
PCNSPL18	18" Spline
PCNMAX12	12" SDS-Max
PCNMAX18	18" SDS-Max
PCNK	12" Kango 950
PCN736	12" 3/4" Hex Skill736, HD45
	
PCNX6	6" “PCN” Shank Extension
PCNX12	12" “PCN” Shank Extension
PCNX18	18" “PCN” Shank Extension
	
PCNSTART	“PCN” Removable Starter Bit

ThunderCore® “PCN” Percussion Core Drills

Part #	Size
PCN1500	1-1/2 x 5"
PCN1750	1-3/4 x 5"
PCN2000	2 x 5"
PCN2500	2-1/2 x 5"
PCN3000	3 x 5"
PCN3500	3-1/2 x 5"
PCN4000	4 x 5"
PCN4500	4-1/2 x 5"
PCN5000	5 x 5"
PCN6000	6 x 6"




Percussion Core “PC” Core Drills

Part #	Size
PC1500	1-1/2"
PC1750	1-3/4"
PC2000	2"
PC2500	2-1/2"
PC3000	3"
PC3500	3-1/2"
PC4000	4"
PC4500	4-1/2"
PC5000	5"
PC5500	5-1/2"
PC6000	6"




Taper Fit

The shank and core drill will permanently become one piece during use.



“PC” Shanks and Accessories

Part #	Description
PCMAX12	12" SDS-Max
PCMAX18	18" SDS-Max
PCSPLINE	12" Spline
PCSPLINE18	18" Spline
PCK	Kango 950 12"
PC637	Kango 637 12"
PC726	12" for 7/16" Hex (726)
PC728	12" for 9/16" Hex (728, 731, 732)
PC736	Skil 736 12"
PCSTARTER	“PC” Removable Starter Bit
	

ThinWall “PCT” Core Drills


Part #	Size
PCT1500	1-1/2"
PCT1750	1-3/4"
PCT2000	2"
PCT2500	2-1/2"
PCT3000	3"
PCT3500	3-1/2"
PCT4000	4"



Excellent for lighter material!



“PCT” Shanks and Accessories

Part #	Description
PCTMAX12	12" SDS-Max
PCTMAX18	18" SDS-Max
PCTSDS8	8" SDS-Plus
PCTSDS12	12" SDS-Plus
PCTSPL12	12" Spline
PCTSPL18	18" Spline
PCTSTART	“PCT” Starter
	

Thin-Wall Rope Thread!